


HORNE TSV1 THERMOSTATIC SHOWER VALVE PIPE FLUSHING PROCEDURE

FIRST:
CHECK THAT SUPPLIES
ARE ISOLATED AT
SERVICING VALVES



SECOND:
REMOVE STRAINER CAPS

