


BATTERY FOR DIGITAL THERMOMETER

0 - 2 BAR PRESS. GAUGE
(WITH PUSH-FIT CONNECTOR)

SURFACE TEMPERATURE PROBE
(USE IMMERSION PROBE IF AT ALL POSSIBLE. IT IS MORE ACCURATE).

PRESSURE GAUGE PROBE
(WITH PUSH-FIT CONNECTOR)



6mm OD NYLON PIPE
(CONNECTS PRESS. GAUGE TO PROBE)

0 - 11 BAR PRESS. GAUGE
(WITH PUSH-FIT CONNECTOR)

DIGITAL THERMOMETER

IMMERSION TEMP. PROBE

BINDER TEST POINTS TO REPLACE
TMV STRAINER CAPS AND PROVIDE
SELF-SEALING PROBE ACCESS INTO
THE HOT & COLD WATER SUPPLIES.

LIQUID SOAP
(PROBE LUBRICANT)

PART :
HORNE TMV MONITORING KIT

PRODUCT :
POINT OF USE TMV's

SCALE	DO NOT SCALE
DRAWN	GDP 5/9/00
CHECKED	
ISSUE	1

THE HORNE ENGINEERING CO. LTD.
JOHNSTONE
RENFREWSHIRE
DR'G. No. 7377B